

Bathroom Inspection - H, B, T, F, P Building
July 15 2015

Location	Light LUX	Notes	Action Required	Status
H Building H123W Mens	42 Sink 18 Toilet	Single use Condition OK	Light levels low.	208 LUX
H Building H125W Womens	44 Sink 29 Toilet	Single use Condition OK	Light levels low.	178 LUX
Location	Light LUX	Notes	Recommendation	Status
H Building H105W Mens	891 Sink. Natural Light 70 Toilet	Counter Stained, Mirror delaminating. Accessible Stall latch broken.	Repair/replace latch. Consider mirror replacement.	
H building H103W Womens	1130 Sink. Natural Light 65 Toilet	Condition OK	None	
B Building B104W Mens	347 Sink 115 Toilet	Sink edge rusting See pictures	Consider replacing sinks	
H Building H131W Mens	362 Sink 96 Toilet	Condition OK	None	
H Building H129W Womens	209 Sink 140 Toilet	Condition OK	None	
B Building B102W Womens	274 Sink 207 Toilet	Sinks could be cleaned better. Stall dirty. See pics	Thorough cleaning required.	
B Building B202W Womens	490 Sink 182 Toilet	No hand soap x2 Sinks have water spots from cleaning.	Refill soap dispensers	
B Building B204W Mens	101 Sink 155 Toilet	No hand soap x1	Refill soap dispensers	
Trades Building T140W Mens	149 Sink 89 Toilet	NO hand soap x 1. Graffiti and Holes in wall. See Pics.	Refill soap. Remove graffiti, repair/paint	
Trades Building T140W womens	353 Sink 392 Toilet	Single use. Walls dirty	Clean walls thoroughly.	
Trades Britco Collision Mens	540 Sink Natural Light 130 Toilet	Dirty. See pics		
Trades Britco Collision Womens	472 Sink 190 Toilet	Condition OK		
F Building F103W Mens	243 Sink 220 Toilet	Condition OK		
F Building F101W Womens	341 Sink 123 Toilet	Conditions OK	None	
F Building F105W Accessible	246 Sink 353 Toilet	Single Use Condition OK	None	

Pictures

<p>B104W Mens</p> 	<p>B102W Womens</p> 	<p>T140W Mens</p> 
<p>T104W Mens</p> 	<p>T104W Mens</p> 	<p>Britco Collision</p> 