

Okanagan College Kelowna

S Building South Inspection

July 6 2015

Location	Description	Hazard	Action	Status
S105D	Users report poor air quality in this area.	M	Users report prompt action by Facilities when requests are made.	
S105L	Storage. Shelving in excess of 8' with heavy objects stored at height. Foot step available.	M		
S109W	Womens Washroom. Users report a sewer smell at times and is remedied by pouring water down the drains. Cleaning Schedule attached to back of door. Daily cleaning.	H	Possible vent/trap issue Vent/Trap W130944-071415	Initiated
S107W	Mens Washroom. Light out. Users report a sewer smell that is remedied by pouring water down the drains. Cleaning schedule attached to back of door. Daily cleaning.	H	Possible Vent Trap issue. W/R for light out. Vent/Trap W130944-071415 Light Repair W130964-071415	Initiated
S109A	Lounge. More than one appliance running causes breaker to trip.	M	W/R to investigate. W130946-071415	Initiated
S109B	Storage Room. Shelves are in excess of 7'. Step available	M	Housekeeping asked to move heavier items to lower areas.	
S109J	Office with kettle and fridge.	M	Revisit appliance policies.	
S109J	Vault. Shelving height in excess of 8' Large items stored high. Loose items stored high.	H	Organize top shelving to remove any hazards.	
S111	Users in this area report air conditioning is more than required.	M	Facilities is working with office users to adjust vent openings.	
S111	Many power bars under desks in work spaces.	M	Investigate with Facilities to find best solution.	